AIR TURQUOISE SA | PARA-TEST.COM

Route du Pré-au-Comte 8 🔺 CH-1844 Villeneuve 🔺 +41 (0)21 965 65 65

Test laboratory for paragliders, paraglider harnesses and paraglider reserve parachutes



Flight test report: EN 926-2:2013 & LTF 91/09

Manufacturer Address	Sky Paragliders a.s. Okružní 39 73911 Frýdlant nad Ostravicí Czech Republic	Certification number Date of flight test		PG_1255.2017 26. 10. 2017	
Glider model	Bi 4 2	Classification		В	
Serial number 2257-11-1209		Representative		None	
Trimmer	yes: closed	Place of test		Villeneuve	
Folding lines used	no				
Test pilot		Thurnheer Claude		Zoller Alain	
Harness		Advance - Bi pro 2		Advance - Bi pro 2	
Harness to risers distance (cm)		44		44	
Distance between ri	sers (cm)	55		55	
Total weight in fligh	· · ·	120		220	
		-			
1. Inflation/Take-off		Α			
Rising behaviour		Smooth, easy and constant rising	A	Smooth, easy and constant rising	А
Special take off technique	required	No	Α	No	А
2. Landing		A	•	No	•
Special landing technique 3. Speed in straight flight		No B	A	No	А
Trim speed more than 30 k		Yes	А	Yes	А
Speed range using the cor		Yes	A	Yes	A
Minimum speed		Less than 25 km/h	A	25 km/h to 30 km/h	В
4. Control movement		Α			
Max woight in flight up t	o 80 kg				
	<i>Max. weight in flight up to 80 kg</i> Symmetric control pressure / travel		0	not available	0
-,,,		not available			
Max. weight in flight 80 kg to 100 kg					
Symmetric control pressure	e / travel	not available	0	not available	0
Max. weight in flight grea	ater than 100 kg				
Symmetric control pressure	e / travel	Increasing / greater than 65 cm	А	Increasing / greater than 65 cm	А
5. Pitch stability exiting a		0			
Dive forward angle on exit		not available	0	not available	0
Collapse occurs		not available	0	not available	0
flight	g controls during accelerated	0			
Collapse occurs		not available	0	not available	0
7. Roll stability and damp	bing	A		B + ·	
Oscillations	-1-	Reducing	A	Reducing	A
8. Stability in gentle spira Tendency to return to strain		A Spontaneous exit	А	Spontaneous exit	А
9. Behaviour exiting a ful		A	А		~
Initial response of glider (fi		Immediate reduction of rate of turn	A	Immediate reduction of rate of turn	А
Tendency to return to straig	ght flight	Spontaneous exit (g force decreasing, rate of turn decreasing)	A	Spontaneous exit (g force decreasing, rate of turn decreasing)	A

Turn angle to recover normal flight	Less than 720°, spontaneous recovery	A	Less than 720°, spontaneous recovery	А
10. Symmetric front collapse	A		,	
Approximately 30 % chord				
Entry	Rocking back less than 45°	А	Rocking back less than 45°	Α
Recovery	Spontaneous in less than 3 s	А	Spontaneous in less than 3 s	А
Dive forward angle on exit Change of course	Dive forward 0° to 30° Keeping course	A	Dive forward 0° to 30° Keeping course	А
Cascade occurs	No	А	No	А
Folding lines used	No		No	
At least 50% chord				
Entry	Rocking back less than 45°	А	Rocking back less than 45°	Α
Recovery	Spontaneous in less than 3 s	А	Spontaneous in less than 3 s	А
Dive forward angle on exit / Change of course	Dive forward 0° to 30° / Keeping course	Α	Dive forward 0° to 30° / Keeping course	А
Cascade occurs	No	А	No	А
Folding lines used	No		No	
With accelerator				
Entry	not available	0	not available	0
Recovery	not available	0	not available	0
Dive forward angle on exit / Change of course	not available	0	not available	0
Cascade occurs	not available	0	not available	0
Folding lines used	Not available		Not available	
11. Exiting deep stall (parachutal stall)	Α			
Deep stall achieved	Yes	А	Yes	А
Recovery	Spontaneous in less than 3 s	А	Spontaneous in less than 3 s	А
Dive forward angle on exit	Dive forward 0° to 30°	А	Dive forward 0° to 30°	А
Change of course	Changing course less than 45°	Α	Changing course less than 45°	A
Cascade occurs	No	A		A
12. High angle of attack recovery	A			
Recovery	Spontaneous in less than 3 s	А	Spontaneous in less than 3 s	А
Cascade occurs	No	А	No	А
13. Recovery from a developed full stall	A			
Dive forward angle on exit	Dive forward 0° to 30°	А	Dive forward 0° to 30°	А
Collapse	No collapse	Α	No collapse	A
Cascade occurs (other than collapses)	No	A	No	A
Rocking back	Less than 45°	A	Less than 45°	A
Line tension	Most lines tight	A	Most lines tight	A
14. Asymmetric collapse	B		moot moo agin	
	-			
Small asymmetric collapse				
Change of course until re-inflation / Maximum dive forward or roll angle	Less than 90° / Dive or roll angle 0° to 15° $$	A	Less than 90° / Dive or roll angle 0° to 15°	A
Re-inflation behaviour	Spontaneous re-inflation	А	Spontaneous re-inflation	А
Total change of course	Less than 360°	А	Less than 360°	А
Collapse on the opposite side occurs	No (or only a small number of collapsed cells with a spontaneous reinflation)	A	No (or only a small number of collapsed cells with a spontaneous reinflation)	A
Twist occurs	No	А	No	А
Cascade occurs	No	А	No	А
Folding lines used	No		No	
Large asymmetric collapse				
Change of course until re-inflation / Maximum dive forward or roll angle	90° to 180° / Dive or roll angle 15° to 45°	В	90° to 180° / Dive or roll angle 15° to 45°	В
Re-inflation behaviour	Spontaneous re-inflation	А	Spontaneous re-inflation	А
Total change of course	Less than 360°	А	Less than 360°	А

Collapse on the opposite side occurs	No (or only a small number of collapsed cells with a spontaneous reinflation)	A	No (or only a small number of collapsed cells with a spontaneous reinflation)	A
Twist occurs	No	А	No	А
Cascade occurs	No	А	No	А
Folding lines used	No		No	
Small asymmetric collapse with fully activated accelerator				
Change of course until re-inflation / Maximum dive forward or roll angle	not available	0	not available	0
Re-inflation behaviour	not available	0	not available	0
Total change of course	not available	0	not available	0
Collapse on the opposite side occurs	not available	0	not available	0
Twist occurs	not available	0	not available	0
Cascade occurs	not available	0	not available	0
Folding lines used	Not available		Not available	
Large asymmetric collapse with fully activated accelerator				
Change of course until re-inflation / Maximum dive forward or	not available	0	not available	0
roll angle		U		U
Re-inflation behaviour	not available	0	not available	0
Total change of course	not available	0	not available	0
Collapse on the opposite side occurs	not available	0	not available	0
Twist occurs	not available	0	not available	0
Cascade occurs	not available	0	not available	0
Folding lines used	Not available		Not available	
15. Directional control with a maintained asymmetric	Α			
collapse				
Able to keep course	Yes	А	Yes	А
180° turn away from the collapsed side possible in 10 s	Yes	А	Yes	А
Amount of control range between turn and stall or spin	More than 50 % of the symmetric control travel	А	More than 50 % of the symmetric control travel	A
16. Trim speed spin tendency	A			
Spin occurs	No	А	No	А
17. Low speed spin tendency	A			
Spin occurs	No	А	No	А
18. Recovery from a developed spin	A			
Spin rotation angle after release	Stops spinning in less than 90°	А	Stops spinning in less than 90°	А
Cascade occurs	No	А	No	А
19. B-line stall	Α			
Change of course before release	Changing course less than 45°	А	Changing course less than 45°	А
Behaviour before release	Remains stable with straight	А	Remains stable with straight span	А
	span			
Recovery	Spontaneous in less than 3 s	А	Spontaneous in less than 3 s	А
Dive forward angle on exit	Dive forward 0° to 30°	А	Dive forward 0° to 30°	А
Cascade occurs	No	А	No	А
20. Big ears	Α			
Entry procedure	Dedicated controls	А	Dedicated controls	А
Behaviour during big ears	Stable flight	А	Stable flight	А
Recovery	Spontaneous in less than 3 s	А	Spontaneous in less than 3 s	А
Dive forward angle on exit	Dive forward 0° to 30°	А	Dive forward 0° to 30°	А
21. Big ears in accelerated flight	0			
Entry procedure	not available	0	not available	0
Behaviour during big ears	not available	0	not available	0
Recovery	not available	0	not available	0
Dive forward angle on exit	not available	0	not available	0
Behaviour immediately after releasing the accelerator while	not available	0	not available	0
maintaining big ears				

22. Alternative means of directional control	Α		
180° turn achievable in 20 s	Yes	A Yes	А
Stall or spin occurs	No	A No	Α
23. Any other flight procedure and/or configuration described in the user's manual	0		
Procedure works as described	not available	0 not available	0
Procedure suitable for novice pilots	not available	0 not available	0
Cascade occurs	not available	0 not available	0
24 Comments of test silet			

24. Comments of test pilot

Comments